


MAPAL Turning inserts with PCBN



DCMW...

Description	Dimensions (mm)				PCBN																			
					FJC1A0		FJD1A0		FJE1A0		FJF1A0		FJG1A0		FJH1A0		FJJ1A0		FJK1A0		FJL1A0		FJM1A0	
	d	s	r	d1	Cutting edges		Cutting edges		Cutting edges		Cutting edges		Cutting edges		Cutting edges		Cutting edges		Cutting edges					
				F01	T35	F01	T44	F01	T42	F01	T43	F01	T35	F01	T44	F01	T48	F01	T43	F01	T43	F01	T46	
DCMW 070201 ...N-OAA	6,35	2,38	0,1	2,8			o	o							o	o							o	o
DCMW 070202 ...N-OAA	6,35	2,38	0,2	2,8	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o
DCMW 070204 ...N-OAA	6,35	2,38	0,4	2,8	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o
DCMW 070208 ...N-OAA	6,35	2,38	0,8	2,8	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o
DCMW 110302 ...N-OAA	9,52	3,18	0,2	4,4	o	o							o	o										
DCMW 110304 ...N-OAA	9,52	3,18	0,4	4,4	o	o							o	o		o	o	o	o	o	o	o	o	o
DCMW 110308 ...N-OAA	9,52	3,18	0,8	4,4	o	o							o	o		o	o							
DCMW 11T301 ...N-OAA	9,52	3,97	0,1	4,4			o	o						o	o								o	o
DCMW 11T302 ...N-OAA	9,52	3,97	0,2	4,4	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o
DCMW 11T304 ...N-OAA	9,52	3,97	0,4	4,4	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o
DCMW 11T308 ...N-OAA	9,52	3,97	0,8	4,4	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o
DCMW 11T312 ...N-OAA	9,52	3,97	1,2	4,4			o	o						o	o								o	o
DCMW 150404 ...N-OAA	12,7	4,76	0,4	5,5	o	o							o	o		o	o	o	o	o	o	o	o	o
DCMW 150408 ...N-OAA	12,7	4,76	0,8	5,5	o	o							o	o		o	o	o	o	o	o	o	o	o




DCMW...

Wiper

Description	Dimensions (mm)				PCBN																			
					FJD1A0		FJH1A0		FJM1A0															
	d	s	r	d1	Cutting edges		Cutting edges		Cutting edges															
				W01	W48	W01	W48	W01	W62															
DCMW 070201 ...R/L-OAA	6,35	2,38	0,1	2,8	o	o	o	o	o	o														
DCMW 070202 ...R/L-OAA	6,35	2,38	0,2	2,8	o	o	o	o	o	o														
DCMW 070204 ...R/L-OAA	6,35	2,38	0,4	2,8	o	o	o	o	o	o														
DCMW 11T301 ...R/L-OAA	9,52	3,97	0,1	4,4	o	o	o	o	o	o														
DCMW 11T302 ...R/L-OAA	9,52	3,97	0,2	4,4	o	o	o	o	o	o														
DCMW 11T304 ...R/L-OAA	9,52	3,97	0,4	4,4	o	o	o	o	o	o														
DCMW 11T308 ...R/L-OAA	9,52	3,97	0,8	4,4	o	o	o	o	o	o														

MAPAL Turning inserts with PCBN



DCMW...

Description	Dimensions (mm)				PCBN														
	d	s	r	d1	FJC1A0		FJE1A0		FJF1A0		FJG1A0		FJJ1A0		FJK1A0		FJL1A0		
					Cutting edges		Cutting edges		Cutting edges		Cutting edges		Cutting edges		Cutting edges				
					F01	T35	F01	T42	F01	T43	F01	T35	F01	T48	F01	T43	F01	T43	
DCMW 070202 ...N-OAB	6,35	2,38	0,2	2,8		o				o	o		o		o		o		
DCMW 070204 ...N-OAB	6,35	2,38	0,4	2,8		o		o		o	o		o		o		o		
DCMW 070208 ...N-OAB	6,35	2,38	0,8	2,8		o				o	o		o		o		o		
DCMW 11T302 ...N-OAB	9,54	3,97	0,2	4,4	o	o				o	o	o		o		o	o	o	
DCMW 11T304 ...N-OAB	9,54	3,97	0,4	4,4	o	o		o		o	o	o		o		o	o	o	
DCMW 11T308 ...N-OAB	9,54	3,97	0,8	4,4	o	o				o	o	o		o		o	o	o	



DCMW...

regrindable

Description	Dimensions (mm)				PCBN														
	d	s	r	d1	FJC1A0		FJE1A0		FJF1A0		FJG1A0		FJJ1A0		FJK1A0		FJL1A0		
					Cutting edges		Cutting edges		Cutting edges		Cutting edges		Cutting edges		Cutting edges				
					F01	T35	F01	T42	F01	T43	F01	T35	F01	T48	F01	T43	F01	T43	
DCMW 11T302 ...N-OAA...-R	9,52	3,97	0,2	4,4	o	o		o		o	o	o		o		o	o	o	
DCMW 11T304 ...N-OAA...-R	9,52	3,97	0,4	4,4	o	o		o		o	o	o		o		o	o	o	
DCMW 11T308 ...N-OAA...-R	9,52	3,97	0,8	4,4	o	o		o		o	o	o		o		o	o	o	
DCMW 150404 ...N-OAA...-R	12,7	4,76	0,4	5,5		o								o				o	
DCMW 150408 ...N-OAA...-R	12,7	4,76	0,8	5,5		o								o				o	

Order example:

Please state the reference with the cutting edge and PCBN grade selected in your order.

DCMW 11T302 T35 N-OAA-FJC1A0-R